

Bob Johnson
Sr. Designer 1
Compliance and Regulatory Affairs

DAIMLER

Daimler Trucks North America LLC
4747 N. Channel
Portland, Oregon 97217-7699
503-745-5076 Phone
503-745-5544 Fax
Bobjohnson@freightliner.com

March 20, 2014

National Highway Traffic Safety Administration
Attention: VIN coordinator

Via Fax (202) 493-0073

Subject: Amended VIN Coding

In accordance with Part 565.7, Daimler Trucks North America submits the following new VIN deciphering information.. Please list these changes under the WMI of 1FV and 1FU.

VIN position 5 and 6 Model, Cab, GVWR for Freightliner

Engine, Fuel, Displacement and Brakes *Position 7 & 8*

Code	Engine	Fuel	Displacement	Config.	Brakes
D2	DD8	Diesel	7.7 Liter	I-6	Air
D3	DD8	Diesel	7.7 Liter	I-6	Hydraulic
FA	DD5 (previously reported as MDEG 5.1L)	Diesel	5.1 Liter	I-4	Hydraulic
FB	DD5 (previously reported as MDEG 5.1L)	Diesel	5.1 Liter	I-4	Air

You may call me at (503) 745-5076 or fax at (503) 745-5544 if more information is needed.

Sincerely,



Bob Johnson
Sr. Designer 1